Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/12012NW0359/1

Work Order Type: Weatherization

Audit Name: Audit-12012NW0359

CLIENT INFORMATION

Client Name: 12012NW0359 **Address:**

Client ID: 12012NW0359 , 38341

Alt. Client ID: Benton

CLIENT CONTACT INFORMATION

12012NW0359 Applicant/Person of Record ☑

AGENCY INFORMATION

Agency: Northwest TN EDC **Agency Phone:** (731) 364-3228

Address: 231 S. Wilson Street **Fax:**

Dresden, TN 38225 **Email Address:**

Company Name & License Number: _____

Contractor's Signature: _____

COMMENT

Contractor to follow the Southeast Field Guide as applicable.

Measures

Measure 1   **Repair Damaged Wall Under and Between Windows in Master Bedroom on Left**   *Components*   *Inspected*

Comment Remove all damaged drywall and insulation. Treat previously wet area with a EPA registered microban.
Install new insulation (and air seal under and around window as explained in General Air Sealing).
Install drywall over previously damaged area (approx. 16 sq. ft)

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Labor			1					
2	Miscellaneous Su			1					

Other Detail

Measure Sub Total: **Sub Total:**

Field Notes:

Measure 2   **Replace and Reframe Front Door DR1 with Lock Set**   *Components*   *Inspected*

Comment Existing door does not latch and is a major safety issue. Approx. 36 x 80

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Labor			1					
2	Doors			1					

Other Detail

Measure Sub Total: **Sub Total:**

Field Notes:

Client Name: 12012NW0359   **Work Order (Bid Form)**   DOE Weatherization Assistant
Client ID: 12012NW0359   Work Order Name: WO/12012NW0359/1   Version 8.6.0
Alt. Client ID: Benton   Report Run On: 5/24/2010   Page 2 of 7

Measure 3 **Replace Floor Insulation and Blanket (approx. 200 sq ft)**   *Components*   *Inspected*

Comment

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Labor			1					
2	Miscellaneous Su			1					

Other Detail

Measure Sub Total: _____   *Sub Total:* _____

Field Notes:

Measure 4 **Weatherstrip Around All Doors**   *Components*   *Inspected*

Comment

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Labor			1					
2	Doors			1					

Other Detail

Measure Sub Total: _____   *Sub Total:* _____

Field Notes:

Measure 5 General Air Sealing   Components   *Inspected*

Comment -Air seal around all windows and clear caulk around exterior of windows. (Pay special attention to windows in master bedroom)
-Air seal trim around all doors
-Air seal plumbing penetrations under bathtub
-Air seal board under plumbing in laundry room
-Air seal new wall in master bedroom (that was previously damaged and will be reinstalled by contractor)

#	Material / Labor	Description / Comment	Units	Estimated Qty	Estimated Unit Cost	Estimated Total	Actual Qty	Actual Unit Cost	Actual Total
1	Insulation	General air sealing (setup cost)	Each	1					
10	Miscellaneous Su	Infiltration Reduction	Each	1					

Other Detail

Measure Sub Total: [ ]   **Sub Total:** [ ]

Field Notes:

Measure 6 DWH Pipe Insulation   Components   *Inspected*

Comment

#	Material / Labor	Description / Comment	Units	Estimated Qty	Estimated Unit Cost	Estimated Total	Actual Qty	Actual Unit Cost	Actual Total
1	Insulation	DWH Pipe Insulation	Each	1					
2	Labor	DWH Pipe Insulation	Each	1					

Other Detail

Measure Sub Total: [ ]   **Sub Total:** [ ]

Field Notes:

Client Name: 12012NW0359   **Work Order (Bid Form)**   DOE Weatherization Assistant
Client ID: 12012NW0359   Work Order Name: WO/12012NW0359/1   Version 8.6.0
Alt. Client ID: Benton   Report Run On: 5/24/2010   Page 4 of 7

Measure 7   DWH Tank Insulation   Components   *Inspected*

Comment

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DWH Tank Insulation	Each	1					
2	Labor	DWH Tank Insulation	Each	1					

Other Detail

Measure Sub Total: ____   **Sub Total:** ____

Field Notes:

Measure 8   2 Smoke Detectors are Needed   Components   *Inspected*

Comment

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety	Smoke detector	Each	1					
2	Labor	Labor	Hour	1					

Other Detail

Measure Sub Total: ____   **Sub Total:** ____

Field Notes:

Measure 9 Clean Blower and Coils (Evaporator and Condenser)

Components

Inspected

Comment

#	Material / Labor	Description / Comment	Units	Estimated Qty	Estimated Unit Cost	Estimated Total	Actual Qty	Actual Unit Cost	Actual Total
1	Labor			1					
2	Heating Equipmen			1					

Other Detail

Measure Sub Total: _____ **Sub Total:** _____

Field Notes:

Measure 10 CO Monitor is Needed

Components

Inspected

Comment

#	Material / Labor	Description / Comment	Units	Estimated Qty	Estimated Unit Cost	Estimated Total	Actual Qty	Actual Unit Cost	Actual Total
1	Health and Safety	CO monitor	Each	1					
2	Labor	Labor	Hour	1					

Other Detail

Measure Sub Total: _____ **Sub Total:** _____

Field Notes:

Client Name: 12012NW0359
Client ID: 12012NW0359
Alt. Client ID: Benton

Work Order (Bid Form)
Work Order Name: WO/12012NW0359/1
Report Run On: 5/24/2010

DOE Weatherization Assistant
Version 8.6.0
Page 6 of 7

Measure **11 Replace Return Filter**   *Components*   *Inspected*

Comment Include Extra Filters

#	Material / Labor	Description / Comment	Units	Estimated			Actual		
				Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Labor			1					
2	Heating Equipmen			1					

Other Detail

Measure Sub Total: *Sub Total:*

Field Notes:

Work Order Grand Total: *Grand Total:*